



**Office of the  
Assistant Engineer  
Public Works Department  
Lower Subansiri, Arunachal Pradesh**

No.....PWD/BSC/ZVS/17/2026


Dated: 28<sup>th</sup> May 2026

**BUILDING SAFETY CERTIFICATE**

Certified that the existing building RCC Building at Ziro Valley School, Lempia, Lower Subansiri district, Arunachal Pradesh comprised of 130 feet x 36 feet basement(s) and 130 feet x 36 feet upper floors owned by Ziro Valley School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Work Department, Lower Subansiri District, Arunachal Pradesh on **28<sup>th</sup> May 2026** in the presence of Mr. Rubu Tadii, Chairman, Ziro Valley School and that the building/premises is fit for occupancy upto classes X with effect from 27<sup>th</sup> May 2026 for a period of 3 (Three) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The building Structure shall be maintained in safe and stable condition at all times and any structural damage noticed in future shall be repaired immediately.
2. Adequate fire safety measures such as fire extinguishers, emergency exits and electrical safety precautions shall be installed and maintained as per national Building Code and Fire Safety norms.
3. The School authority shall not make any unauthorized alternation, extension or additional construction in the building without prior approval from the competent authority.
4. The occupancy of classrooms and school premises shall remain within the permissible limit prescribed under CBSE Affiliation Bye-laws and National Building Safety norms.
5. The school management shall ensure periodic inspection of electrical wiring, sanitary facilities, drinking water system and disaster management arrangement for safety of students and staff.
6. The building shall be used only for educational purposes and all safety guidelines issued by CBSE, State government and concerned authorities shall be strictly followed.
7. The school authority shall maintain proper ventilation, emergency evacuation arrangements and unobstructed entry and exit passage in all parts of the building.
8. This certificate shall remain valid subject to proper maintenance of the building and compliance with all applicable safety norms and regulations during the validity period.

Issued on 28<sup>th</sup> May 2026 at Office by

  
Assistant Engineer  
Public Work Department  
H.Q, Ziro Division  
Lower Subansiri Distt. (A.P.)  
Assistant Engineer  
Public Work Department  
Lower Subansiri District  
Arunachal Pradesh